

Attorney Docket No. 1594.1309

NITED STATES PATENT AND TRADEMARK OFFICE

ATTENTION

BRANCH

CERTIFICATE OF CORRECTION

In re Patent Application of:

Jin Baek KIM et al.

Application No.: 10/748,229

Confirmation No.: 7130

Filed: December 31, 2003

U.S. Patent No.: 7,066,712

Issued: June 27, 2006

For:

TURBOFAN AND AIR CONDITIONER HAVING THE TURBOFAN

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 USC § 254 and 37 CFR § 1.322, to correct the error(s) shown on the attached Form PTO-1050. A check in the amount of \$100 to cover the cost of the Certificate is attached.

One or more of the errors shown on the attached Form PTO-1050 is or are within the responsibility of the applicant; each thereof is of a clerical or typographical nature or of minor character and occurred in good faith, and the correction thereof is consistent with the prosecution record.

Respectfully submitted,

STAAS & HALSEY LLP

By:

Gene M. Garner, II

Registration No. 34,172

1201 New York Ave, N.W., 7th Floor

Dec. 5, 2006

Washington, D.C. 20005 Telephone: (202) 434-1500 Facsimile: (202) 434-1501

OF FC:00810

DEC 1 1 2005

of Correction

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO: 7,066,712 DATED: June 27, 2006

INVENTOR(S): Jin Baek KIM et al.

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 7, Line 31, after "coupled" insert --to--.

Column 7, Line 38-39, after "direction and" delete "of an axial direction and".

MAILING ADDRESS OF SENDER: STAAS & HALSEY LLP 1201 New York Avenue, N.W. 7th Floor Washington, DC 20005 PATENT NO. 7,066,712

No. of add'l copies @ 304 per page